


Ideen aus der Praxis!

MEIER-BRAKENBERG

Einweichenanlagen
Hochdruckreiniger
Tierwaagen

Low-floor scale WASTN

Instruction Manual



MEIER-BRAKENBERG GmbH & Co. KG

Brakenberg 29 • 32699 Extertal

Tel: +49(0)52 62/993 99-0 • Fax: +49(0)52 62/993 993

E-Mail: info@meier-brakenberg.de

Online: www.meier-brakenberg.de


INSTRUCTION FOR MOBILE AND STATIONARY WEIGHING MACHINES


Mobile and stationary animal scales from MEIER-BRAKENBERG are exclusively suitable for weighing pigs and sheep. The stationary scales may be loaded up to a weight of 1,500 kg. For legal-for-trade scales, the maximum weighing range is indicated on a sticker on the weighing display.

The animal scales may only be operated by trained personnel!

To open front gates of stationary scale, use foot-pedal.

The electronics are preset for the weighing of fattening pigs. This basic setting made by Meier-Brakenberg does not need to be changed. The scale is ready for operation. However, the setting can be changed using the following operating instructions. This can be useful, for example, for the exact weighing of non-moving goods. Before using the battery for the first time, fully charge it in accordance with the instructions. The display shows low battery power. If the battery needs to be charged, a battery symbol appears on the right of the display.

For animal weighing, all values must be maintained in accordance with the basic settings in the operating instructions and should not be adjusted. To zero the balance, briefly press the  button until '0' appears on the display again.

By using animal weighing mode, it's important that all base settings of operators manual will be retaining and not be switched. To reach zero, please press button .

Cleaning scale

Weighing box may be cleaned with water. For quality safety, display with connection cables and weighing bars should not be exposed to high-pressure cleaning. Clean display with damp cloth.

Direction

No welding work may be carried out on the device or in the immediate vicinity. This can lead to damage to the electronics. Welding work may only be carried out if the display and weighing beam are completely dismantled. The electronics may only be operated in accordance with the following operating instructions.

Note:

We are also happy to manufacture other mobile or stationary scales for you in various sizes and designs. Give us a call!


Scope of delivery:	mobile scales	- Adapter power-supply, integrated battery
	Fixed scales	- Adapter power-supply

ASSEMBLY OF LOW-FLOOR WEIGHING MACHINE

Unpacking



1. Fit toe clips.



2. Position cap pieces.
3. Tilt over in horizontal position.



3. Remove outer plank packing, take out single components
4. Before assembling side parts: determine position. Push the side part with outer face pre-assembled cable duct into that side of the base plate on which the cables with the display protrude.

Assembly of side parts



1. Loosen screw on remote control side and sink in side rail to assemble side part (for later screw-connection).



2. Insert evenly into side rail of base plate.



3. Assembly of side parts:
- with 7 screws 10 x 60 + nuts; each rail 2 pieces to upper drill-holes;
Exception: side with remote control pedal, this side up only 1 screw
- and 3 screws 10 x 80 + nuts; each rail 1 piece to lowest drill-hole;
Exception: side with remote control opening no screw at bottom

4. Connect junction plate with 8 screws 8 x 20 and 8 nuts M8
Adjustment of doors (if necessary)



Adjustment of door openers: close door, adjust nuts under the handle until the bar of the door opener is in the lowest possible position above the inclined base plate, tighten nut afterwards.

Assembly of display and cable duct




1. Mount display holder with 2 screws 8 x 50 - screw display to holder.
2. Pull two cables at a time through the cable duct at the side part of the weighing machine. Mind exact laying to allow cover to open!
3. Position cover of cable duct flush to the cable and duct end and clip sideways.

OPERATION OF LOW-LEVEL WEIGHING MACHINE

Weighing process


1. Open doors drive cattle into weighing machine, close doors.
2. Balance calculates the average weight and shows total weight on display (marked with „L“).
3. Actuate remote control pedal to open doors on opposite side. NOTE: Doors open automatically by means of spring power.
4. Drive out cattle.



OPTIONALLY: 2nd remote control for entrance door; for cattle drive through from both sides!

Carrier (optionally)

1. Lift weighing machine with the carrier lever by hooking into the provided loop (center of front side); hook by passing lever in between the doors.
2. Clip wheels: lift handle and insert wheel unit into base plate. Note: Mind drill hole in base plate; locking mechanism of pivots/ bolt of wheel unit.
3. Lift weighing machine with the carrier lever at opposite side; the weighing machine is now ready to be moved by using the lever.
4. Disassembly: lift weighing machine at wheel end and remove wheels.



☞ **If you have any further question concerning weighing, don't hesitate to contact us! Tel.: +49(0)52 62/993 99-0**

State: 05.07.2022

Copyright

For this document Meier-Brakenberg GmbH & Co. KG reserves all rights. Reproduction, disclosure to third parties or use of its contents is prohibited without our express consent.

© 2018

Nameplate

The following nameplate is attached to the display:



The nameplate is a document and must not be removed from the display.

FOREWORD

These operating instructions provide you with detailed information about the Display WA400.

These instructions contain safety instructions to guarantee safe use of the volume and weight measurement system.

The manufacturer strives to improve their products on an ongoing basis. They reserve the right to carry out any and all modifications and improvements that they consider to be necessary. However, this means that there is no obligation to carry out retrospective modifications in this connection.



Danger

Before using the Display WA400, you must have read and understood the operating instructions and the safety regulations that they contain.



Note

Errors and omissions in the documentation reserved. If necessary, please inform Meier-Brakenberg GmbH & Co. KG of any errors in the documentation. We would also be grateful for any suggestions for improvements that you may have.

The manufacturer's contact data is listed on the reverse of the title page. If you have any queries or problems, please contact the manufacturer without delay.



Note

Have your serial number to hand when contacting Meier-Brakenberg GmbH & Co. KG.

CONTENTS

FOREWORD 1

1 Safety 4

 1.1 For your safety 4

 1.1.1 General 4

 1.1.2 Safety symbols in this manual 5

 1.2 Intended use 5

 1.3 Obligations of the owner/user 5

 1.4 Obligations of the operator..... 6

 1.5 Description of the dangers 6

 1.5.1 Danger of injury..... 6

 1.5.2 Danger of damages 6

 1.6 Liability and warranty 6

2 Description 8

 2.1 Layout 8

 2.2 Display 10

 2.2.1 Display overview..... 10

 2.2.2 Legend for the weighing value display..... 11

 2.3 Keyboard overview..... 12

3 Transport, commissioning/start-up and tests/inspections 14

 3.1 Control..... 14

 3.2 Packaging and disposal 14

 3.3 Regular inspections/checks 14

 3.4 Testing equipment monitoring..... 14

 3.5 Extraordinary inspections..... 15

 3.6 Repair work..... 15

 3.7 Use other than the intended..... 15

 3.8 Commissioning / start-up 16

 3.9 Charging the rechargeable battery..... 17

 3.10 Safety information for handling rechargeable batteries and power cables . 18

4 Operation 20

 4.1 Switching on and off..... 20

 4.1.1 Switching on..... 20

 4.1.2 Switching off..... 20

 4.2 Weighing process..... 21

 4.3 Control weighing 21

 4.3.1 Switching on and off the signal light..... 21

 4.3.2 Setting the limit 21

 4.4 Factory-set limit values 24

 4.4.1 Limit values for the mobile scales..... 24

 4.4.2 Limit values for the animal group scales..... 24

5 Settings 26

 5.1 Main menu 26

 5.1.1 Adjustment with weight 26

 5.1.2 Theoretical adjustment..... 30

 5.1.3 Adjustment correction 34

 5.1.4 Reset to factory-settings 34

 5.1.5 Setting the time and date..... 36

 5.2 Quick selection menu..... 38

 5.2.1 Setting the background lighting..... 38

6 Troubleshooting	42
6.1 In the event of a malfunction.....	42
6.2 Error messages of the scales.....	42
6.3 Customer service contact data.....	42
6.4 Information for the contact to the customer service	43
7 Technical data	44
7.1 Type plate for a Stationary display.....	44
7.2 Type plate for a mobile display	44
7.3 Technical drawing	45
7.4 Technical data.....	46
7.5 Scope of delivery / Wiring diagram.....	46
8 Menu overview	48
8.1 Navigation in the menu	48
8.2 Function menu overview	48
8.3 Menu protected by a password.....	51
8.4 Quick selection menu (HLG menu).....	55
9 Declaration of Conformity	58
9.1 Declaration of Conformity for scales not calibrated.....	58

1 SAFETY

This chapter warns against possible risks when handling the device. The information for detection of risks contained in this chapter is intended to allow the safe and correct operation.



It is important to read and adhere to this operating manual and particularly this chapter prior to operating this device.

1.1 FOR YOUR SAFETY

1.1.1 GENERAL

In addition to safety information, the operating manual includes:

- A general product description
- Information about installation and connection of the device
- Instructions to operate the device
- Maintenance and care instructions
- Troubleshooting and remedy instructions
- Technical data

Always keep this operating manual and additional documents for your personnel at hand in the direct vicinity of the device.

Always adhere to all information, notes, instructions and explanations contained in this manual! Avoid accidents caused by incorrect operations! Also adhere strictly to the valid legal regulations in addition to the safety instructions specified in this manual.

Prior to commissioning/start-up read the safety information/instructions and familiarise yourself with dangerous areas.

The device is constructed according to the current state of art and the valid safety regulations. However, there are risks in the event of incorrect operation or non-observance of the safety regulations:

- Danger to limb and life of operators, third persons and animals staying in the vicinity of the device.
- Danger to the device and other assets of the owner/user
- Danger to the efficient operation of the device.

1.1.2 SAFETY SYMBOLS IN THIS MANUAL

The following symbols are used on all important positions in this manual. Particularly observe these notes and treat very careful.



Danger

This note indicates danger of injuries and/or danger to life, if specific behaviour rules are not observed.

When this symbol appears in the operating manual, please take all required safety measures.



Attention

This note warns against damage to assets as well as financial disadvantages and responsibility under criminal law (e.g. loss of the warranty, cases of third party risks, etc.).



Note

Important notes and information about an efficient, economic and environmental friendly handling are specified here.

1.2 INTENDED USE

The Display WA400 exclusively serves to display the weight in combination with suitable weighing cells.

Any further use is considered as not in accordance with the intended use. The manufacturer does not assume any liability for resulting damage.

The intended use also includes:

- Observance of all notes, information, instructions contained in the documentation as well as in all supplied manuals issued by the manufacturer.
- Adherence of the maintenance and service conditions and intervals prescribed by the manufacturer and
- Observance of the technical data.

Adhere to the attendant accident prevention regulations as well as other generally approved technical safety rules.



Note

Always specify the serial number of your display for all questions, orders or jobs. This will facilitate the communication with the manufacturer and prevents error during editing your request.

1.3 OBLIGATIONS OF THE OWNER/USER

The owner/user obligates himself to only instruct persons to work on the device, who:

- Are familiar with the basic rules concerning safety and accident prevention and are trained in the operation of this device and
- have read and understood the operating manual, the safety chapter as well as the warning notes.

1.4 OBLIGATIONS OF THE OPERATOR

All persons instructed to operate the device obligate themselves:

- to always ensure the safety of other persons,
- to read the operating manual, the safety chapter and the warning notes and
- to only operate the device when they are familiarised with its functions.

1.5 DESCRIPTION OF THE DANGERS

1.5.1 DANGER OF INJURY

- Always switch off the device for care and maintenance work.
- Never insert any pointed objects into the electric contacts.
- Do not change the contacts.
- Stop device operation, if the device or the connection line is damaged or have a malfunction.

1.5.2 DANGER OF DAMAGES

- Only connect the device to suitable weighing cells (see chapter 3.6 “Interfaces”).
- Never use pointed objects to actuate the device keys.

1.6 LIABILITY AND WARRANTY

Meier-Brakenberg offers a restricted warranty for components, which became faulty due to strain or material faults. The warranty starts with the date of delivery. Meier-Brakenberg retains the right to repair or replace components. Repair work executed during the warranty period will not extend the period of warranty. The warranty becomes null and void:


- In the event of incorrect use / use other than the intended use or incorrect installation
- Incorrect electric connection
- Use of an incorrect or non-licensed analogue / digital converter
- Non-observance of the specifications in the operating manual
- Conversion, modification or opening of the device
- Unintentional or mechanical damage and damage caused by media, liquids, natural wear.

2 DESCRIPTION


2.1 LAYOUT

The Display WA400 is a control system and display used to operate an animal scales and to determine the weight of animals. The weighing results can be saved or transmitted.

An integrated signal light optically supports product weighing.



Item	Designation
1	Integrated signal light
2	Housing
3	Mounting screws (3 pieces)
4	Cover for loading cable connection
5	Cable fittings
6	USB connection






Item	Designation
1	USB connection
2	Screw plugs (4 pieces)




2.2 DISPLAY

The displays of the individual animal scales (ETW) series offers all advantages of quick and accurate weighing. The keyboard is water-proof and the LCD displays are equipped with background lighting as a standard. All displays have a zero function, a three-colour signal light and a sum memory, which allows saving of individual weighing processes and invoking them as a total sum.

2.2.1 DISPLAY OVERVIEW

The LCD display indicates a value (0,0) and a weighing unit (kg). Further labelling is G for gross and stable  or .



W1	Scales 1
	Zero positioning, sets the zero point for all following weighing processes. Zero is displayed.
G	Gross weighing is displayed.
	Animal weighing function
	Stability display, lights up when the weight is placed stable.
kg	Active weight unit


2.2.2 LEGEND FOR THE WEIGHING VALUE DISPLAY





A	B	C	D	E	F	G	H	I	J	K	L	M
H	b	c	d	e	f	u	h	,	u	h	L	

N	O	P	Q	R	S	T	U	V	W	X	Y	Z
n	o	p	q	r	s	t	u	v	w	x	y	z

0	1	2	3	4	5	6	7	8	9
0	1	2	3	4	5	6	7	8	9

2.3 KEYBOARD OVERVIEW



Key	User level	Function level
	The current weight on the scales is saved.	The activated number during parameter value setting or setting of other functions can be displaced to the left. ◀
	When a USB stick is connected, the data are transmitted to the stick. For this purpose, press the "MR_TRANSFER" key for two seconds. The sum of the saved individual weighing processes and the resulting total weight are displayed. To delete individual weighing results simultaneously press the keys "M+" and "MR_TRANSFER" (MC).	The activated number during parameter value setting or setting of other functions can be increased. ▲
	If the keys "LIMIT" and "ON/OFF_TARE" are actuated simultaneously, the saving process is cancelled.	Apply the input during parameter value setting or setting of other functions. ↵ ENTER
	Used to switch on and off the display device. For switch off, press the key "ON/OFF_TARE" for two seconds, OFF appears in the display.	Leaving the function level. ESC

3 TRANSPORT, COMMISSIONING/START-UP AND TESTS/INSPECTIONS

3.1 CONTROL

When the display is delivered, check the packaging, the device and possible accessories for visible damages.

3.2 PACKAGING AND DISPOSAL

Keep all parts of the original packaging for a possible return.



Note

Only use the original packaging, if the display is returned.
Prior to the transport, disconnect/fasten all loose/moving parts of the device.
Secure the parts against slipping/damage.

Dispose of the packaging and the display according to the national and/or local regulations by law valid on the installation site. Separately dispose of a defective battery according to the national and local regulations on environmental protection and recycling.

Do not treat a battery as standard waste. Please dispose of via a waste management company.

3.3 REGULAR INSPECTIONS/CHECKS

Check the display for visible damage, prior to each use. Also check electric lines for damage, prior to each use. If defectives can be detected, immediately stop operating and any other work on the display or the electric lines and contact an authorised expert.

3.4 TESTING EQUIPMENT MONITORING

Quality assurance requires regular inspections of the technical measuring features of the display in connection with the scales and a possible available test weight. The owner/user can define a suitable interval as well as the scope of these inspections.

3.5 EXTRAORDINARY INSPECTIONS

After special incidents, the display must be additionally inspected visually by an authorised person (even if not within the regular inspection interval).

Inspection criteria

- Correct function of the display.
- Damages to the housing.
- Damages to electric lines and connectors.

If defectives can be detected, immediately stop operating and any other work on the display or the electric lines and contact an authorised expert.

3.6 REPAIR WORK

Only the manufacturer or persons instructed by the manufacturer are allowed to carry out repair work on the display.

The electronic components are not completely water-proof and must not come into contact with splash water or being immersed. If the electronic components become wet or visible damages can be detected, stop operating the scales.

If spare parts or accessories are required, please contact your supplier.

3.7 USE OTHER THAN THE INTENDED

- Protect the electronic display unit against humidity. Particular protection is required during cleaning work.
- If small amounts of the goods to be weighed are removed or added, incorrect weighing results might appear caused by the “Stability compensation” integrated in the scales!
- Never modify the design of the display. This can lead to incorrect weighing results, technical safety defects as well as the destruction of the display.
- Only use the display in accordance with the described specifications



Danger

**Never operate the display in potentially explosive atmosphere.
The display is not explosion protected.**

- Only use original spare parts.



Attention

The design/construction of the product as well as all regulations (standards, etc.) specified in the operating manual refer to the directives valid in Germany. Only use the product in other countries in accordance with the directives, regulations and laws valid in the country of use.


Only use original spare parts!

3.8 COMMISSIONING / START-UP


Keep the device clean and do not expose to an environment influencing the display accuracy.




Protect against draught!



Protect against heat, sun frost!



Protect against tilting vibration!



Avoid unstable voltage sources!



Avoid humidity!

Observe the following, prior to commissioning/starting up:

Ensure that the weight on the scales does not exceed the maximum load!



Note

Allow a short heat-up time to stabilise the display (approx. 15 minutes).



Note

Ensure that a 230 V AC voltage supply is available on the installation site (unless operation with rechargeable batteries is intended).

3.9 CHARGING THE RECHARGEABLE BATTERY



- Connect the mains cable to the loading cable connection (1) and insert the connector in the socket.
 - The charging process automatically starts.
 - The battery symbol lights up on the display as long as the battery is charging.

Complete charging of a completely discharged battery takes approx. 4 hours at 23°C. The charging period depends on the ambient temperature and the charging status of the battery. The charging might take longer, if the temperature is lower.

Charge the battery on the day of use or the day before. Batteries are also discharged during storage, even if not used.

The power pack can also be used in other countries. It can be connected to voltage sources with 100 to 240 V alternating current and 50/60 Hz. If necessary, use a common socket adapter for the respective country. Never connect any mobile voltage converters, otherwise, the power pack and the display could be damaged.



Note

The battery is worn, if the voltage decreases quickly after charging. Contact the responsible expert.

3.10 SAFETY INFORMATION FOR HANDLING RECHARGEABLE BATTERIES AND POWER CABLES

Only use batteries, power sources or accessories intended for this use by the manufacturer.

Never use batteries designed or modified by yourself.

Never short-circuit rechargeable batteries, disassemble them or modify them in any manner.

Ensure that the battery does not in contact with heat, soldering material, fire or water.

Ensure that the battery is not inserted opposite to the specified polarity direction (+/-). Do not simultaneously use new and old batteries or different battery types.

Only charge the rechargeable battery within the admissible ambient temperature range. Do not exceed the charging time.

Do not insert any foreign objects made of metal into the electric contacts of the display, accessory parts, connection cables, etc..

Never store batteries in the vicinity of children. Immediately contact a doctor when your child has swallowed up the battery.

Prior to disposing of the rechargeable battery, insulate the contacts with tape to avoid direct contact to objects made of metal. In this manner, you can prevent a fire.

If the battery or the power pack heat up excessively during charging, immediately interrupt the process by disconnecting the connector of the battery charging unit.

Immediately remove the battery when liquid or gel emerges. If the battery changes its colour or shape, disconnect it from the scales or the power pack. Be particularly careful to avoid burning injuries.

Contact with the battery fluid can lead to skin irritations and/or blindness. If emerged fluid comes into contact with eyes, skin or clothing, immediately rinse the area in question thoroughly with water. Subsequently see a doctor.

Never store cables in the vicinity of heat sources. This can deform cables and damage their insulation leading to the danger of electrocution or fire.

Never use the display and the charging unit in the vicinity of highly flammable gas.

Do not disassemble or modify the display.

Do not store the display in moist or dusty environment.

If the scales drops into water or water ingresses the housing, immediately remove the battery.

Never cover the power packs or charging units with cloths or wrap cloths around them. This might result in heat accumulation.

Ensure that the connector is completely inserted in the socket.

Never touch charging and mains cable with wet hands.

Pull the mains cable on the connector out of the socket (not on the cable).

Ensure that power cables are not damaged, cut, kinked or loaded with heavy objects. Never twist or interlace cables. Prior to using cable drums, unwind the cable completely. Do not connect too many connectors to one socket. Do not use any cables with damaged insulation.


Regularly disconnect the connector from the socket and remove any soiling and dust from the connector and the socket environment.

Close the charging socket of the display with the protective cap when no charging unit is connected.

4 OPERATION

4.1 SWITCHING ON AND OFF

4.1.1 SWITCHING ON




- Press the key (4) “ON/OFF_TARE”.
 - The display is switched on.
 - The software version is displayed.
 - Then a display self test is made and the scales automatically sets to “0.0”.
- The display has an automatic function to reset the scales to zero. If the scales displays small numbers, press the key (4) “ON/OFF_TARE”. Weighing starts at zero.

4.1.2 SWITCHING OFF

- Press the key (4) “ON/OFF_TARE” for two seconds.
 - “oFF” appears briefly in the display.
 - The display is switched off.

4.2 WEIGHING PROCESS

- Place the goods to be weighed on the weighing plate. For animals wrangle the animals into the scales.
 - The stability display appears with stable values 



- If the goods to be weighed are heavier than the set weighing range, "E.OLP" (= overload) appears on the display.



4.3 CONTROL WEIGHING

The control weighing can be used to check the weight of individual animals. The three-colour signal light additionally indicates whether or not the weighed animals are too light or too heavy.

4.3.1 SWITCHING ON AND OFF THE SIGNAL LIGHT

- Press the key (3) "LIMIT" for two seconds.
 - The status of the signal light briefly appears on the display.
Status "ON": The signal light is activated.
Status "OFF": The signal light is deactivated.

4.3.2 SETTING THE LIMIT

- Briefly press the key (3) "LIMIT".
 - The following message appears in the display:



- Activation of the setting for the limit values of the yellow LEDs.
- Briefly press the key (3) "LIMIT" again.

- The display changes over to the value input:

A digital display showing the number 001070 in a seven-segment font.

- The RH display flashes.
- Press the key (2) "MR_TRANSFER" to change the value.
- Press the key (1) "SAVE" to go on by one digit to the left and change the value.
- Press the key (3) "LIMIT" to confirm the value for the yellow LEDs.
 - This message briefly appears in the display:

A digital display showing the word "done" in a stylized font.

- Activation of the setting for the limit values of the red LEDs.
- The following message appears in the display:

A digital display showing the text "L 17-r" in a stylized font.

- Briefly press the key (3) "LIMIT".
 - The display changes over to the value input:

A digital display showing the number 001130 in a seven-segment font.

- The RH display flashes.
- Press the key (2) "MR_TRANSFER" to change the value.
- Press the key (1) "SAVE" to go on by one digit to the left and change the value.
- Press the key (3) "LIMIT" to confirm the value for the red LEDs.
 - This message briefly appears in the display:

A digital display showing the word "done" in a stylized font.

- Activation of the setting for the limit values of the blue LEDs.
- The following message appears in the display:

A rectangular digital display showing the text "L 17-8" in a monospaced font.

- Briefly press the key (3) "LIMIT".
 - The display changes over to the value input:

A rectangular digital display showing the text "00 1190" in a monospaced font.

- The RH display flashes.
- Press the key (2) "MR_TRANSFER" to change the value.
- Press the key (1) "SAVE" to go on by one digit to the left and change the value.
- Press the key (3) "LIMIT" to confirm the value for the blue LEDs.
 - This message briefly appears in the display:

A rectangular digital display showing the text "done" in a monospaced font.

- Activation of the setting for the limit values of the green LEDs.
- The following message appears in the display:

A rectangular digital display showing the text "L 17-6" in a monospaced font.

- Briefly press the key (3) "LIMIT".
 - The display changes over to the value input:

A rectangular digital display showing the text "00 1250" in a monospaced font.

- The RH display flashes.
- Press the key (2) "MR_TRANSFER" to change the value.

- Press the key (1) "SAVE" to go on by one digit to the left and change the value.
- Press the key (3) "LIMIT" to confirm the value for the green LEDs
 - This message briefly appears in the display:



- The display automatically switches to weighing mode.

4.4 FACTORY-SET LIMIT VALUES

4.4.1 LIMIT VALUES FOR THE MOBILE SCALES

- 0 kg - 106.4 kg: no LEDs are light up (the weight is smaller than LIN-y)
- 106.5 kg - 112.4 kg: The yellow LEDs lights up (LIN-y \leq Weight value < LIN-r)
- 112.5 kg - 118.4 kg: The red LEDs lights up (LIN-r \leq Weight value < LIN-B)
- 118.5 kg - 124.4 kg: The blue LEDs lights up (LIN-B \leq Weight value < LIN-G)
- \geq 125.5 kg: The green LEDs lights up (LIN-G \leq Weight value)

4.4.2 LIMIT VALUES FOR THE ANIMAL GROUP SCALES

- < 107 kg: no LEDs lights up (the weight is smaller than LIN-y)
- 107 kg - 112 kg: The yellow LEDs lights up (LIN-y \leq Weight value < LIN-r)
- 113 kg - 118 kg: The red LEDs lights up (LIN-r \leq Weight value < LIN-B)
- 119 kg - 124 kg: The blue LEDs lights up (LIN-B \leq Weight value < LIN-G)
- \geq 125.5 kg: The green LEDs lights up (LIN-G \leq Weight value)

5 SETTINGS

5.1 MAIN MENU

5.1.1 ADJUSTMENT WITH WEIGHT

According to the basic physical weighing principle at the installation site, each scales must be adjusted to the conditions on site such as gravity acceleration, temperature, location, etc.

- Ensure that no load is on the scales.
- Switch on the scales using the key “ON/OFF_TARE”.
- Press the key <ENTER> while the scales counts down.
 - The following message appears in the display:

The image shows a rectangular LCD display with a black border. Inside, the text 'CON 1' is displayed in a white, segmented, digital font. 'CON' is on the left and '1' is on the right, separated by a small gap.

- Press the key <LEFT>.
 - The following message appears in the display:

The image shows a rectangular LCD display with a black border. Inside, the text 'Code' is displayed in a white, segmented, digital font.

- Press the key <ENTER>.
 - The message “- - - -” appears on the display.
- Enter the code “0000” using the keys <UP> and <LEFT>.
 - The <UP> key is used to change a value.
 - The <LEFT> key is used to change between the individual numbers.
- Confirm the code using the key <ENTER>.
 - The message (setting) appears on the display:

The image shows a rectangular LCD display with a black border. Inside, the text 'SET 179' is displayed in a white, segmented, digital font. 'SET' is on the left and '179' is on the right, separated by a small gap.

- Press the key <UP>.

- The message (CAL/calibration) appears on the display:

A rectangular display box containing the text "CAL" in a monospaced, digital font.

- Press the key < ENTER >.
 - The message (SPAN/two-point calibration) appears on the display:

A rectangular display box containing the text "SPAN" in a monospaced, digital font.

- Press the key < ENTER >.
 - The message (Raw/raw measured value) appears on the display:


A rectangular display box containing the text "rAU" in a monospaced, digital font.

- Press the key < ENTER >.
 - The current raw measured value of the A/D converter appears on the display:

Example 

A rectangular display box containing the numerical value "38550" in a monospaced, digital font.

- Press the key < ENTER > or < ESC >.
 - The message (Raw/raw measured value) appears again on the display:

A rectangular display box containing the text "rAU" in a monospaced, digital font.

- Press the key < UP >.
 - The message (Zero) appears on the display:

A rectangular display box containing the text "Zero" in a monospaced, digital font.

- Press the key < ENTER >.

- The current raw measured value of the A/D converter appears on the display.

Example 

- Ensure that not load is on the scales.
- Briefly wait (until the displayed value hardly changes) and then confirm the value with the key <ENTER>.
 - The message “donE” briefly appears on the display.
 - The message (Zero) appears again on the display:



- Press the key <UP>.
 - The message (Load/load weight) appears again on the display:



- Press the key < ENTER>.
 - The currently set value of the load appears flashing on the display.
- Enter a value for the load using the keys <UP> and <LEFT> :

Example 

- Confirm the value using the key <ENTER>.
 - The current raw measured value of the A/D converter appears on the display.

Example 

- Ensure that the set load is on the scales.
- Press the key < ENTER>.

- The message "donE" briefly appears on the display.
- The message (Load/load weight) appears again on the display:



- Press the key <ESC> repeatedly to leave the menu.
 - The message (Save ?) appears on the display:



- Press the key <ENTER>, if the value is to be saved.
 - The messages "donE" and "off" briefly appear on the display.
 - The scales is switched off.
- Press the key <ESC>, if the value is not to be saved..
 - The message "off" briefly appears on the display.
 - The scales is switched off.

5.1.2 THEORETICAL ADJUSTMENT

- Switch on the scales using the key “ON/OFF_TARE”.
- Press the key <ENTER> while the scales counts down.
 - The following message appears in the display:

A rectangular digital display showing the text 'CON 1' in a seven-segment font.

- Press the key <LEFT>.
- The following message appears in the display:

A rectangular digital display showing the text 'Code' in a seven-segment font.

- Press the key <ENTER>.
 - The message “- - - -” appears on the display.
- Enter the code “0000” using the keys <UP> and <LEFT>.
- Confirm the code using the key <ENTER>.
 - The message (setting) appears on the display:

A rectangular digital display showing the text 'SET 179' in a seven-segment font.

- Press the key <UP>.
 - The message (CAL/calibration) appears on the display:

A rectangular digital display showing the text 'CAL' in a seven-segment font.

- Press the key <ENTER>.
 - The message (SPAN/two-point calibration) appears on the display:

A rectangular digital display showing the text 'SPAN' in a seven-segment font.

- Press the key <UP>.

- The message (theoretical calibration) appears on the display:

A rectangular display showing the text 'nU-U' in a monospaced, digital font.

- Press the key < ENTER >.
- The message (field calibration/calibration with known weighing cells) appears on the display:

A rectangular display showing the text 'FIELD' in a monospaced, digital font.

- Press the key < ENTER >.
- The message (sensitivity) appears on the display:

A rectangular display showing the text 'SENS' in a monospaced, digital font.

- Press the key < ENTER >.
- Enter a value using the keys < UP > and < LEFT > for the weighing cell sensitivity.

Example

A rectangular display showing the text '38550' in a monospaced, digital font.

- Press the key < ENTER >.
- The message "donE" and the following message briefly appear on the display again:

A rectangular display showing the text 'SENS' in a monospaced, digital font.

- Press the key < UP >.
- The message (maximum load) appears on the display:

A rectangular display showing the text 'LCAP' in a monospaced, digital font.

- Press the key < ENTER >.

- Enter a value using the keys <UP> and <LEFT> for the maximum capacity of the weighing cell.

Example 

- Press the key < ENTER>.
 - The message “donE” and the following message briefly appear on the display again:



- Press the key <UP>.
 - The message (Zero) appears on the display:



If necessary, a new zero point of the scales can be adjusted here.

- Press the key < ENTER>.
 - The current raw measured value of the A/D converter appears on the display:

Example 

- Press the key < ENTER>.
 - The message “Wait” (Wait) briefly appears on the display and the message(Zero) again:



- Press the key <ESC> twice to leave the menu.
 - The message (gravity/gravity factor) appears on the display:



If necessary, the gravity factor (gravity acceleration) can be adapted here.

- Press the key < ENTER>.
 - The value for the gravity acceleration appears on the display.

A digital display showing the value 98.1276 in a seven-segment font.

- Enter the value for the gravity acceleration of the respective installation location here.
- Press the key < ENTER>.
 - The message “donE” and the following message briefly appear on the display again:

A digital display showing the message GrAvItY in a seven-segment font.

- Press the key <UP>.
 - The message (calibration method) appears on the display:

A digital display showing the message CALSEL in a seven-segment font.

- Press the key < ENTER>.
 - The calibration method (field) activated last appears on the display:

A digital display showing the message FIELd in a seven-segment font.

- Press the key <UP>.
 - The message (Factory) appears on the display:

A digital display showing the message FAcTrY in a seven-segment font.

- Press the key <UP>.

- The message (SPAN) appears on the display:



- Actuate the key <ENTER> to activate the desired calibration method.
 - The message “donE” briefly appears on the display.
 - The message (calibration method) appears again on the display:



- Press the key <ESC> repeatedly to leave the menu.

5.1.3 ADJUSTMENT CORRECTION

If the displayed value of the theoretical adjustment (factory-set default value) deviates from the value of the real weight, this value can be corrected.

- Simultaneously actuate the keys <UP> and <LEFT> for approx. three seconds.
 - The RH digit of the displayed weight starts flashing.
- Correct the value using the keys <UP> and <LEFT>.
 - The <UP> key is used to change a value.
 - The <LEFT> key is used to change between the individual numbers.
- Confirm the value using the key <ENTER>.
 - The message “donE” briefly appears on the display.

This correction can be repeated as often as required.

5.1.4 RESET TO FACTORY-SETTINGS

- Switch on the scales using the key “ON/OFF_TARE”.
- Press the key <ENTER> while the scales counts down.
 - The following message appears in the display:




- Press the key <LEFT>.

- The following message appears in the display:



- Press the key < ENTER >.
 - The message “- - - -” appears on the display.
- Enter the code “0000” using the keys < UP > and < LEFT >.
 - The < UP > key is used to change a value.
 - The < LEFT > key is used to change between the individual numbers.
- Confirm the code using the key < ENTER >.
 - The message (setting) appears on the display:



- Press the key < UP > four times.
 - The message (reset) appears on the display:



- Press the key < ENTER >.
- Use the < UP > key to navigate.
 - The messages “ON” or “OFF” appear on the display.
- Actuate the “ON” message using the < ENTER > key.
 - The display is reset to factory-settings.



When the system is reset to factory-settings all settings made after delivery will be lost!


5.1.5 SETTING THE TIME AND DATE

The scales is equipped with an internal clock.

- Switch on the scales using the key “ON/OFF_TARE”.
- Press the key <ENTER> while the scales counts down.
 - The following message appears in the display:



- Press the key <UP> three times.
 - The message (Time) appears on the display:




- Press the key <ENTER>.
 - The message (hour) appears on the display:



- Press the key <ENTER>.
 - The value currently set appears on the display and starts flashing.
- Correct the hours using the keys <UP> and <LEFT>.
 - The <UP> key is used to change a value.
 - The <LEFT> key is used to change between the individual numbers.
- Confirm the value using the key <ENTER>.
 - The display automatically changes over to the input of the “Min.” value.
- Correct the minutes using the keys <UP> and <LEFT>.
- Confirm the value using the key <ENTER>.
 - The display automatically changes over to the input of the “Sec.” value.
- Correct the seconds using the keys <UP> and <LEFT>.
- Confirm the value using the key <ENTER>.

- The display automatically changes over to the input of the “Day” value.
- Correct the days using the keys <UP> and <LEFT>.
- Confirm the value using the key <ENTER>.
 - The display automatically changes over to the input of the “Month” value.
- Correct the months using the keys <UP> and <LEFT>.
- Confirm the value using the key <ENTER>.
 - The display automatically changes over to the input of the “Year” value.
- Correct the year using the keys <UP> and <LEFT>.
- Confirm the value using the key <ENTER>.
 - The message “donE” briefly appears on the display.
 - The message (Time) appears again on the display:

A rectangular digital display showing the word "Time" in a segmented, seven-segment font. The letters are white on a dark background.

- Press the key <ESC>.
 - The message (Save ?) appears on the display:

A rectangular digital display showing the text "SAVE ?" in a segmented, seven-segment font. The letters are white on a dark background.

- Press the key <ENTER>, if the value is to be saved.
 - The messages “donE” and “off” briefly appear on the display.
 - The scales is switched off.
- Press the key <ESC>, if the value is not to be saved.
 - The message “off” briefly appears on the display.
 - The scales is switched off.

5.2 QUICK SELECTION MENU

5.2.1 SETTING THE BACKGROUND LIGHTING

- Ensure that no load is on the scales.
- Switch on the scales using the key “ON/OFF_TARE”.
- Press the key <LEFT> for two seconds.
 - The message (High-Low-Go-Mode) appears on the display:



- Press the key <UP> five times.
 - The message (Display) appears on the display:



- Press the key <ENTER>.
 - The message (Background lighting) appears on the display:



- Press the key <ENTER>.
- Use the <UP> key to navigate.
 - The message (Background lighting: Automatic/On/Off) appears on the display:



- Press the key <ENTER> when “bL AU” is displayed.

- The time (seconds) for background lighting can be entered here.
- The message (Background lighting) appears on the display:

A digital display showing the text "BL 120" in a seven-segment font. The "BL" is on the left and "120" is on the right.

- Press the key <UP> several times.
 - The displayed value is changed (10 - 120). The time value "120" displays the seconds, for which the display (inactivity of weight) remains active.
- Press <ENTER>.
 - The message "donE" briefly appears on the display.
 - The following message appears again in the display:

A digital display showing the text "BL 194E" in a seven-segment font. The "BL" is on the left and "194E" is on the right.

- Press the key < ENTER>.
- Use the <UP> key to navigate.
 - Following messages appear on the display:

A digital display showing the text "bL AU" in a seven-segment font. The "bL" is on the left and "AU" is on the right.

A digital display showing the text "bL on" in a seven-segment font. The "bL" is on the left and "on" is on the right.

A digital display showing the text "bL oFF" in a seven-segment font. The "bL" is on the left and "oFF" is on the right.

- Press the key <ENTER> when "bL On" is displayed.
 - The background lighting is always ON.
- Press the key <ENTER> when "bL Off" is displayed.
 - The background lighting is always OFF.
 - The message "donE" briefly appears on the display.

- The following message appears again in the display:



- Press the key <ESC> repeatedly to leave the menu.

6 TROUBLESHOOTING

6.1 IN THE EVENT OF A MALFUNCTION

We recommend switching off the scales briefly and disconnecting it from the mains, if a malfunction occurs in the program sequence. Then restart the weighing process.

6.2 ERROR MESSAGES OF THE SCALES

Error message	Description	Possible cause
E.016	No USB stick connected.	No USB stick available.
E.040	No data for transmission available.	No values saved in the long-term memory.
--OL--	Overload	The maximum set weighing range is exceeded.
Err.Lin	Error Limit Hi and LOW values incorrectly defined.	The set HI value is smaller than the set LOW value.
ErrScL	After switching on and the display self test no digitalisation unit is detected. The scales do not switch to weighing mode.	The scales is not connected.
Er2Ero	The weight is not added to the sum memory during weighing.	The scales is not zeroed prior to the weighing process →0← .

If any other malfunctions or error messages occur, please switch off the scales and after a short while on again.

If error messages occur again, please contact the customer service.

6.3 CUSTOMER SERVICE CONTACT DATA

Meier-Brakenberg GmbH & Co. KG
 Brakenberg 29
 D-32699 Extertal

Phone +49 5262993990
 Fax +49 5262993948
 Email info@meier-brakenberg.de

6.4 INFORMATION FOR THE CONTACT TO THE CUSTOMER SERVICE

Owner/user	Specifications
Name of your company	
Name of a contact person	
Contact data	Telephone Fax Email

Tabelle 6.1: Your company

Product	Specifications
Model name	
Serial number	
Type key	
Date of purchase	
Name and location of the supplier	

**Note**

Fill in the table shown above when the display is delivered to be able to use all information without any problems at any time.

Information about the problem:

Examples for required specifications to support troubleshooting:

- Does the display operate fault-free since its delivery?
- Has the display any contact to water?
- Was there any damage due to a fire?
- Was there a thunderstorm before / during the malfunction?

**Note**

Please inform us about the entire history of the display.

7 TECHNICAL DATA


7.1 TYPE PLATE FOR A STATIONARY DISPLAY




7.2 TYPE PLATE FOR A MOBILE DISPLAY




7.3 TECHNICAL DRAWING




SA Rechts1




Vordans2



SA Links2



Drfsicht2



Rckans2

7.4 TECHNICAL DATA

Feature	Value / Unit
Type	Rechargeable lithium-ion battery
Dimensions (W x H x D)	182,5 x 156 x 75 mm
Weight Aluminium housing Power supply (external)	Approx. 1.5 kg 12 VDC / 230 VAC, 1000 mA via external mains adapter
Service life of rechargeable battery	Up to 12 hour in permanent operation
Charging time of rechargeable battery	Approx. 4 hours
Adjustment	Automatic, external
Max. resolution (depending on the weighing cells used) Display	External 1/30,000 Internal 1/1,000,000 6 digits, LCD illuminated, Digit height 30 mm
Keyboard	4 pressure point keys
Interface(s) (2 as an option)	RS485, Lan, RS232
Functions	Weighing value display, sum memory, presettable weighing with alarm, control signal lights
Weighing cell sensitivity Number of weighing cells AD converter	1mV/V~3mV/V Up to 4 with 350 Ohm each 24 bits, 1 channel
Zero input range Signal input range Settling time	0mV~5mV 0mV~15mV 2 seconds typical
Operating temperature Relative air humidity	+5°C to +40°C max. 80%, non-condensing

7.5 SCOPE OF DELIVERY / WIRING DIAGRAM

Component	Note
Display / Weighing terminal	
Mains adapter	
Operating manual	
Table/wall holder	Not included for the version with stand

	E+	E-	L	S+	S-
Mobile Scales: (WA400MM) WA18, WA08, WAS, WAF, WASA, WAF, WAKF, etc.	red	black	Shield (blue)	white	green
Stationary Scales: (WA400MS) WASTN	green	black	Shield (blue)	white	red



Connecting terminal



Mobile Scales



Stationary Scales

8 MENU OVERVIEW

8.1 NAVIGATION IN THE MENU

- A menu or subroutine is left by pressing the key <ESC>.
- The <UP> key is used to navigate between the individual menu points and modify editable numbers.
- The key <LEFT> serves to move the input cursor to the left by one digit.

8.2 FUNCTION MENU OVERVIEW

Actuate the <ENTER> key (or <LIMIT>) after the display has been switched on and while the countdown on the display counts down.

Menu	Subroutine	Options	Function
COM1	Mode 1	Off, CONT, ST1,ST2, STC, PR1, PR2, PR3, ASK	
		Cont (continuously transmits data)	
	Outp	PC // data string Print 1// Print 2 // HPP-250 Print 3 // LP-50 Print 4 // HPP-250 for HLS lifting carriages Print 5 // HP083 Remote display „rntdSP“// external large display (RD50, RD100, RD150, RD195) Lights // external three-colour light (PC0, PCL, PCG, PCH) (Status lamp SL3)	Protocol setting (Printer type)
	Baud 1	1200, 2400, 4800, 9600, 14400, 19200, 28800, 38400, 57600, 115200,	Data transmission speed (Baud rate)
	Part 1	8n1 //8 Data bytes, No Parity, 1 Stop Bit 7E1 // 7 Data bytes, Even Parity, 1 Stop Bit 7O1 //7 Data bytes, Odd Parity, 1 Stop Bit	Parity settings (for data transmission)
	Ntw.Rst	Network reset No Yes	The WLAN settings can be reset.

Menu	Subroutine	Options	Function
COM 2	As COM 1	As COM 1	As COM 1
USB	Multpl	// Alibi data blocks: the data blocks of all days are written in one file during saving on the USB stick.	Setting of the saving method of measured data on the USB stick.
	Single	// Alibi data blocks: an individual file is created for each measuring day during saving on the USB stick.	
Time	Hour, Min, Sec, Day, Month, Year		Setting of time and date.
FUNC	Units	SEL 0: no weight unit SEL 1: g (gram) SEL 2: kg (kilogram) SEL 3: t (ton) SEL 4: lb (pound)	Weight unit selection.
	Ext.Dev:	Off Gyro	“External Device” selection (is not used!).
SPEED	SMPLNG	6, 12, 25, 50, 100, 200	ADC sampling rate Sampling rate of the external ADC (Attention: The setting does usually not require any changes! Effect on the weight calculation!).

Menu	Subroutine	Options	Function
LEGAL	ALB.SW (Alibi Switch)	AI.On AI.Off	Saving weight data in the internal memory (sum memory or alibi memory).
	ALB.SHW (Alibi Show)	EDIT.AB (Edit Alibi Number) "000000" // 0 flashing --> Selection of the alibi entry.	Show alibi entry (show a specific weight value saved in the sum memory).
	GET.LST (Get Last Alibi Number) (Number of Entries) TAC (Tac counter)	"0" // the number of values saved in the sum memory "0" // Number of the executed calibration processes (or number of the storage processes in the menu protected by a password).	
CODE		"- - -" flashing --> CODE = 0000	Change-over to the "Menu protected by a password".

8.3 MENU PROTECTED BY A PASSWORD

- Activation of the main menu
- Navigation to “CODE”
- Enter CODE = 0000 using the keys <UP> and <LEFT> and confirm with <ENTER>

Menu	Subroutine	Options	Function
SETTING	DEC 1	<u>0</u> , 0.0, 0.00, 0.000, 0.0000,	Setting of the desired number of digits after the decimal point.
	INC	<u>1</u> , 2, 5, 10, 20, 50, 100, 200	Increments for the displayed weight (resolution).
	CAP	“ <u>003000</u> ” flashing --> Enter the value using the keys <UP> and <LEFT>	Setting of the maximum capacity.
	OLP	<u>On</u>	“—OVL—” appears when the max. capacity is exceeded.
		Off	Output of the current weight, even if the max. capacity has been exceeded.
	ULP	<u>On</u>	“—OVL—” appears when the min. capacity is gone below.
		Off	Output of the current weight, even if the min. capacity has been gone below.
	RnIn	<u>Off</u> / Rng / Int	Multi-range / Multi-range scales (is not used!).

Menu	Subroutine	Options	Function
CAL	SPAN	<p>Raw "000000"</p> <p>Zero "00000" with <ENTER></p> <p>Load "001000" with <UP> and <LEFT> "000000" set the load point with <ENTER></p>	<p>Two-point calibration (zero point, load point)</p> <p>The current ADC value appears.</p> <p>Set zero point</p> <p>Display / setting of load weight</p>

Menu	Subroutine	Options	Function
CAL	mV - V	FIELD	Theoretical calibration.
		<p>Sens "001000" flashing --> Enter the value using the keys <UP> and <LEFT></p> <p>T.CAP flashing --> Enter the value with <UP> and <LEFT></p> <p>Zero "001000" set the zero point with <ENTER></p>	<p>Setting the sensitivity of the weighing cells used. Stationary: 2.0000 MVV value of the cells (Mobile: 1.7200 for V1.n; 2.0000 for V5.n)</p> <p>Setting the maximum load of the weighing cells used. (Mobile: 1496.0 for stationary: 04535)</p> <p>The current ADC value appears.</p>
		FACTORY (Factory-calbration)	Theoretical calibration using the weighing cell simulator.
		<p>SENS "001000" flashing --> Enter the value using the keys <UP> and <LEFT></p> <p>T.CAP flashing --> Enter the value with <UP> and <LEFT></p> <p>Zero "001000" set the zero point with <ENTER></p> <p>Load "000000" set the load point with <ENTER></p>	<p>Setting the sensitivity.</p> <p>Setting the maximum load.</p> <p>The current ADC value appears.</p> <p>The current ADC value appears.</p>

Menu	Subroutine	Options	Function
CAL	GrAvtY	"981276" flashing --> Set the gravity value with <UP> and <LEFT>	Adaptation of the gravity factor to correct the weight value on the site of scales use. (Default: 9.8130)
	CAL.SEL	<p>SPAN Calibration method = "Span"</p> <p>FIELD Calibration method = "Field"</p> <p>FACTRY Calibration method = "Factory"</p>	Selection of the active calibration method.
Zero - M			Zero menu
		Au.ZERO (Auto Zero) Off / 0.25d / 0.5d / 1d / 2d / 3d / 4d	Set the range for "Zero_Tracking". (Zero tracing function).
		Rn.ZERO (Zero Range) 0, 2, 4, 10, 20, 50, 100	Range, within which the zeroing function can always be carried out (referred in percent to the maximum admissible total weight of the scales).
	On.ZERO (On Zero) 0, 2, 4, 10, 20, 50, 100	Range, within which the zeroing function can be carried out when the scales is switched on (referred in percent to the maximum admissible total weight of the scales)	
Filters	FLT.ACT	On / Off	Filter Active is not used!
RESET		On / Off	Reset to factory-settings

8.4 QUICK SELECTION MENU (HLG MENU)

**Note**

The quick selection menu serves for a facilitated input or reading out parameters and for display parameterisation.

The quick selection menu can be used to set parameters for the function of control weighing cycles, for the alibi memory, the printer, the background lighting and automatic switch-off.

The quick selection menu (while the scales is in weighing mode) can be opened by pressing the key <LEFT> (or <SAVE>) for approx. two seconds.

Menu	Subroutine	Options	Function
HILOGO	HLG.MOD (High-Low-Go - Mode)	Off = three-colour light is deactivated 3-colour = 3-colour mode for the sorting lights 4-colour = 4-colour mode for the sorting lights	Settings for the sorting lights.
	BEEP	Off = acoustic signal deactivated Be OK = acoustic signal in the "Green area" Be Lo = acoustic signal in the "Yellow area" Be Hi = acoustic signal in the "Red area" Be HiLo = acoustic signal in the "Yellow area" and the "Red area" Be OVL = acoustic signal for overload or underload.	Additional acoustic function for the sorting lights (referred to the HLG mode = 3rd colour)
	STORE	On = The HLG limit values are saved. Off = HLG limit values must be set again after a power reset.	Saving the HLG limit values.
	BRIGHT (Brightness)	"Brl.000" flashing --> Enter the value using the keys <UP> and <LEFT> Brightness 0 - 100 %	Settings for the brightness of the sorting lights LEDs. The brightness is subdivided in 32 stages and a change is visible each 3-4 %.

Menu	Subroutine	Options	Function
MEMORY (Sum mem-ory)	Clr.Alb (Clear Alibi Memory)	Clr.No = Do not delete the sum memory Clr.Yes = Delete the sum mem-ory	Deleting the sum mem-ory.
ALIBI	EDIT.AB (Edit Alibi Number)	“000000” flashing --> Enter the value using the keys <UP> and <LEFT>	Display of a specific entry from the sum memory.
	GET.LST (Get Last Alibi Number)	“0” the number of values saved in the sum memory.	
PR1	Info	Number / Alibi / Date / Time / Gross / Net / Tare /T.Gross/ T.Net / T.Tare Confirm On or Off with <ENTER>.	Setting of the individual elements for the print ticket (e.g. whether or not the consecutive number, the date, etc. are to be printed onto the print ticket).
	Copy	Value 0 - 4	Number of the print tick-ets to be printed.
FUNC	APPS (selec-tion of the active applica-tion)	Weight = Standard weight meas-uring Count = Count application PER (Percentage) = Special HLG function (modulation of the sorting lights LEDs depending on only one limit value = 100%) ANIMAL = special animal filtering function is used. PEAK = Peak function is acti-vated. HOLD = Hold function is acti-vated.	Function selection The menu protected by a password cannot be acti-vated while the hold or peak functions are active.

Menu	Subroutine	Options	Function
DISPL	B.Light (Backlight)	<p>BI AU (Backlight Auto) 10 / 20 / 30 / 40 / 50 / 60 / 70 / 80 / 90 / 100 / 110 / 120 --> Set the value with <UP></p> <p>BI On = Background lighting always ON. BI Off = Background lighting always OFF.</p>	<p>Settings for the display (background lighting)</p> <p>Automatic activation / switch-off of the background lighting after N seconds. The background lighting is automatically activated when the weight changes or a key is pressed.</p>
	AU OFF	<p>"AU 00" flashing --> Enter the time (minutes) using <UP> and <LEFT> and confirm with <ENTER>.</p> <p>0 - 99 Value "00" = no switch-off</p>	<p>Automatic switch-off of the scales, if no key is actuated and the weight does not change.</p>
	LNG (Language)	<p>ENG = "G" GEr = "B"</p>	<p>The symbol for gross appears as "G" or "B" on the display.</p>


9 DECLARATION OF CONFORMITY

9.1 DECLARATION OF CONFORMITY FOR SCALES NOT CALIBRATED

 KONFORMITÄT SERKLÄRUNG <i>Declaration of conformity</i> <i>Déclaration de conformité</i> <i>Conformiteitsverklaring</i> <i>Declaración de conformidad</i>		
Typ/Modell: <i>Type/Model – Modèle – Model -Tipo/ Modelo :</i> WA400 / WA400MS	1-2-3 Tierwaage Seriennummern: 1-2-3 Tierwaage2016A001-1-2-3 Tierwaage2016999 <i>Serial numbers - Les numéros de série – Seriennummers -</i> <i>Números seriales: WASTN</i>	
Hersteller: <i>Manufacturer – Fabricant – Fabrikant - Fabrikante:</i>	Meier-Brakenberg GmbH & Co. KG Brakenberg 29 DE-32699 Extertal	

Die alleinige Verantwortung für die Ausstellung trägt der Hersteller.
The sole responsibility for the issue carries the manufacturer - La seule responsabilité de l'exposition porte le fabricant –
De verantwoordelijkheid voor de uitgifte draagt de fabrikant.- El único responsable de la publicación lleva el fabricante.

Die nicht selbsttätige Waage 1-2-3 Tierwaage
The non-automatic weighing instrument – L'instrument de pesage à fonctionnement non automatique –
De niet-automatische weeg – El pesaje de funcionamiento no automático



Der oben beschriebene Gegenstand der Erklärung erfüllt die einschlägigen Harmonisierungsrechtsvorschriften der Union:

2014/30/EG
 2014/35/EU

The object of the declaration described above complies with the relevant Union harmonization legislation:
L'objet de la déclaration décrit ci-dessus est conforme à la législation d'harmonisation de l'Union:
Het doel van de verklaring bovenbeschreven voldoet aan de relevante harmonisatiewetgeving van de Unie:
El objeto de la declaración descrito anteriormente cumple con la legislación de armonización pertinente de la Unión:

entsprechend den folgenden Normen:

in conformity with following standards:
conforme aux norms suivantes:
volgens de volgende normen:
de acuerdo con las siguientes normas:

- EN 55022 :2011-12
- DIN EN 61000-3-3 VDE 0838-3 :2009-06
- DIN EN 55024 VDE 0878-24 :2011-09
- DIN EN 61000-4-2 VDE 0847-4 2 :2009-12
- DIN EN 61000-4-3 VDE 0847-4-3 :2011-04
- DIN EN 61000-4-4 VDE 0847-4-4 :2010-11
- DIN EN 61000-4-5 VDE 0847-4-5 :2007-06
- DIN EN 61000-4-6 VDE 0847-4-6 :2009-12
- DIN EN 61000-4-11 VDE 0847-4-11 :2005-02
- DIN EN 61000-6-3 VDE 0839-6-3 :2011-09
- DIN EN 61000-6-4 VDE 0839-6-4 :2011-09

Unterzeichnet für und im Namen von:

Signed for and on behalf of: - Signé pour et au nom de: - Ondertekend voor en namens: - Firmado por y en nombre de:

Meier-Brakenberg GmbH & Co.KG

Extertal, 20. April 2022

Extertal, 20 April 2022 - Extertal 20 Avril 2022 - Extertal, 20 April 2022 - Extertal, 20 de Abril el año 2022

Wolfgang Meier *Marc Piechnik*

Meier, Wolfgang, Piechnik, Marc, Geschäftsführer - managing director – manager – gerente